

# Contents

	Page
<b>Preface</b> .....	pp iii
<b>Suggestions for Improvement (form)</b> .....	pp iv
<b>A Quality Management Perspective</b> .....	pp 1
<b>Summary Steps for Developing a QA Program</b> .....	pp 6
<b>Tip Sheets and Forms for Addressing DOE Quality Management Criteria</b>	
1. Program. ....	pp 11
2. Personnel Training and Qualification. ....	pp 15
3. Quality Improvement. ....	pp 20
4. Documents and Records. ....	pp 24
5. Work Processes. ....	pp 29
6. Design .....	pp 35
7. Procurement. ....	pp 41
8. Inspection and Acceptance Testing. ....	pp 46
9. Management Assessment. ....	pp 51
10. Independent Assessment. ....	pp 56
<b>Quality Assurance Glossary</b> .....	<b>Appendix A</b>
<b>Guidebook index</b> .....	<b>Appendix B</b>
<b>QM Reference Manual (Available from ESH-14, (505) 665-5437). Throughout the Guidebook text, the following references will be referred to as "QM References":</b>	
1. <i>Quality Management Plan</i> (program requirements document)	
2. 10 CFR 830, "Nuclear Safety Management"(Includes parts 830.1 through 830.120, "Quality Assurance Requirements" ), and <i>Implementation Guide, for use with, 10 CFR PART 830.120 Quality Assurance</i> , G-830.120-REV.0, April 15, 1994.	
3. DOE Order 5700.6C, <i>Quality Assurance, and Attachment I</i>	
4. <i>A comparison of requirements of 10 CFR 830.120, The Rule, and DOE Order 5700.6C, The Order.</i>	
5. DOE Standard, <i>Implementation Guide For Quality Assurance Programs for Basic and Applied Research</i> , DOE-ER-STD-6001-92.	
6. <i>Codes and Standards Applicable to Quality Management: A Partial Annotated List</i>	
7. <i>Policy Requirements Documents</i>	
8. <i>"Calibration Handbook,"</i> Los Alamos National Laboratory publication, LALP-93-47, June 1993.	